

HID® FARGO® HDP®5000

Windows Printer Driver
Release Notes

Driver Version: 3.4.0.6
Driver Part Number: 511191W
PLT-04333, A.4
February 2023



Copyright

© 2021 - 2023 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, HDP, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
February 2023	Update to release notes for driver version 3.4.0.6.	A.4

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the HID® FARGO® HDP®5000 Windows Printer Driver version 3.4.0.6. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

Compatible operating systems:

- Windows 7 x86/x64
- Windows 10 x86/x64
- Windows 11 x64
- Windows Server 2012 R2 x64
- Windows Server 2016
- Windows Server 2019
- Windows Server 2022

1.2 Resolved issues

- Resolved an issue where a link was missing to Korean language for HDP5000 printer driver. (SICPI-1110, TTP-13341)
- Resolved an SDK issue that was setting lamination temperature back to the devmode structure. (SICPI-892)

Revision history

Date	Description	Revision
February 2023	Update to release notes for driver version 3.4.0.6.	A.4
October 2022	Update to release notes for driver version 3.3.0.1	A.3
November 2021	Update to release notes for driver version 3.3.0.1.	A.2
July 2019	Release notes for driver version 3.3.0.1.	A.1
May 2019	Release notes for driver version 3.2.0.16.3.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2023 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04333, Rev. A.4

Part of ASSA ABLOY